




*The specialists in
underwater ship maintenance
SME Award Winner*

PBCE
PBCF

(PROPELLER BOSS CAP FIN)

INSTALLED UNDERWATER IN-SITU



VISIT US AT
Website: www.uwsc.com.sg

PBCF INSTALLATION
REFERENCE PHOTOGRAPH

PHOTOGRAPH SHOWING THE PROPELLER BOSS BEFORE REMOVAL



PBCF INSTALLATION
REFERENCE PHOTOGRAPH

PHOTOGRAPH SHOWING THE PROPELLER BOSS
ON THE BACK OF THE VESSEL



PBCF INSTALLATION
REFERENCE PHOTOGRAPH

PHOTOGRAPH SHOWING THE NEW PBFC
ON THE BACK OF THE VESSEL



PBCF INSTALLATION
REFERENCE PHOTOGRAPH

PHOTOGRAPH SHOWING THE NEW PBFC BEFORE GREASING



**PBCF INSTALLATION
REFERENCE PHOTOGRAPH**

PHOTOGRAPH SHOWING THE NEW PBFC AFTER GREASING



**PBCF INSTALLATION
REFERENCE PHOTOGRAPH**

PHOTOGRAPH SHOWING
THE NEW PBFC BEING LOADED INTO THE WATER



PBCF INSTALLATION
REFERENCE PHOTOGRAPH

PHOTOGRAPH SHOWING THE PROPELLER CONE
AFTER GREASING BY THE DIVERS



**PBCF INSTALLATION
REFERENCE PHOTOGRAPH**

PHOTOGRAPH SHOWING THE NEW PBFC IN POSITION



PBCF INSTALLATION
REFERENCE PHOTOGRAPH

PHOTOGRAPH SHOWING THE NEW PBCF AFTER THE BOLTS
TORQUE WRENCH TO THE SPECIFICATION MANUAL AND
AFTER THE BOLTS WERE SEIZED UP



**PBCF INSTALLATION
REFERENCE PHOTOGRAPH**

PHOTOGRAPH SHOWING THE NEW PBFC IN PLACE AND
AFTER THE RECESSES WERE FILLED WITH UNDERWATER TWO PART
EPOXY CEMENT



PBCF INSTALLATION
REFERENCE PHOTOGRAPH

PHOTOGRAPH SHOWING THE NEW PBFC IN PLACE AND
AFTER THE RECESSES WERE FILLED WITH UNDERWATER TWO PART
EPOXY CEMENT



PBCF INSTALLATION
REFERENCE PHOTOGRAPH

PHOTOGRAPH SHOWING THE NEW PBFC IN PLACE AND
AFTER THE RECESSES WERE FILLED WITH UNDERWATER TWO PART
EPOXY CEMENT BEFORE POLISHING




PBCF INSTALLATION
REFERENCE PHOTOGRAPH

PHOTOGRAPH SHOWING THE NEW PBFC IN PLACE AND
AFTER THE RECESSES WERE FILLED WITH UNDERWATER TWO PART
EPOXY CEMENT BEFORE POLISHING



**PBCF INSTALLATION
REFERENCE PHOTOGRAPH**

PHOTOGRAPH SHOWING THE NEW PBCF IN PLACE AND
AFTER THE RECESSES WERE FILLED WITH UNDERWATER TWO PART
EPOXY CEMENT AFTER POLISHING



**PBCF INSTALLATION
REFERENCE PHOTOGRAPH**

PHOTOGRAPH SHOWING THE NEW PBCF IN PLACE AND
AFTER THE RECESSES WERE FILLED WITH UNDERWATER TWO PART
EPOXY CEMENT AFTER POLISHING



PBCF INSTALLATION
REFERENCE PHOTOGRAPH

PHOTOGRAPH SHOWING THE NEW PBFC IN PLACE AND
AFTER THE RECESSES WERE FILLED WITH UNDERWATER TWO PART
EPOXY CEMENT AFTER POLISHING



PBCF INSTALLATION
REFERENCE PHOTOGRAPH

PHOTOGRAPH SHOWING THE NEW PBCF IN PLACE AND
AFTER THE RECESSES WERE FILLED WITH UNDERWATER TWO PART
EPOXY CEMENT AFTER POLISHING



PBCF INSTALLATION
REFERENCE PHOTOGRAPH

PHOTOGRAPH SHOWING THE NEW PBFC IN PLACE AND
AFTER THE RECESSES WERE FILLED WITH UNDERWATER TWO PART
EPOXY CEMENT AFTER POLISHING AND
SHOWING THE DIVER'S REFLECTION



**PBCF INSTALLATION
REFERENCE PHOTOGRAPH**

PHOTOGRAPH SHOWING THE NEW PBFC IN PLACE AND
AFTER THE RECESSES WERE FILLED WITH UNDERWATER TWO PART
EPOXY CEMENT AFTER POLISHING AND
SHOWING THE DIVER'S REFLECTION



**PBCF INSTALLATION
REFERENCE PHOTOGRAPH**

PHOTOGRAPH TAKEN SHOWING THE ROOT MARKINGS ON
COMPLETION OF THE INSTALLATION AND POLISHING

